Work Order ID 63062 Page 1 Tuesday, October 19, 2010 2:52:55 PM D3941-12 Item ID: Accept Setup Start **Revision ID:** Stop Rubber Cushion Item Name: **Start Date:** 10/19/2010 Start Qty: 5.00 **Cust Item ID: Required Date:** 10/26/2010 Req'd Qty: 5.00 **Customer:** Reference: Run Start **Process Plan:** Date: 10-10-Tooling: **Approvals:** Date: Stop Date: SPC (Y/N): Date: Sequence ID/ **Operation** Set Up/ Tool ID Tool # Plan Reject Accept Reject Insp. Description **Work Center ID** Qty Qty Code Number **Run Hours** Stamp **Revision Nbr Draw Nbr** D3941 Α 100 0.00 Small Fab 0.00 Memo Small Fab **CUT AS PER DWG** 110 QC5- Inspect part completeness to step on W/O 0.00 SB volula QC 0.00 Memo Quality Control Identify as per dwg & Stock Location. 120 0.00 Packaging 0.00 Memo Packaging

W/O:			W	ORK ORDER CHANG	ES	-			<u> </u>		
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
·											
Part No	:	PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQ	A :	_ Date: _			
	R	esolution:	on:	QA: N/C Closed: Date:							
NCR:		\	WORK ORD	DER NON-CONFORMA	ANCE (NCI	R)					
DATE	STEP	Description of NC Section A		Corrective Action Section		Verifi	cation	Approval	Approval		
	JILI		Initial Chief Eng	Action Description Chief Eng	Sign Date		ion C	Chief Eng	QC Inspector		
									1		

Work Order ID 63062

Required Date: 10/26/2010

Tuesday, October 19, 2010 2:52:55 PM



Page 2

Item ID:

D3941-12

Accept



Setup Start

Stop



Revision ID:

Item Name:

Rubber Cushion

Start Date:

10/19/2010

Start Qty: 5.00

Req'd Qty: 5.00



Cust Item ID:

Customer:

Reference:

A		
ΑĐ	prova	us:

QC: _

Process Plan: _____

Operation

Description

Date:_____

Date: Tooling:

SPC (Y/N):

Set Up/

Run Hours

Date:

Date:

Run Start

Stop



Sequence ID/

Work Center ID

130

Memo

QC21- Final Inspection - Work Order Release

Tool ID

Tool # Plan

Accept Code Qty

Reject Qty

Reject

Insp. Number Stamp

WF 10-10-21.

Quality Control

0.00

0.00

W/O:			W	ORK ORDER CHANG	ES						
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector		
· · · · · ·			The state of the s								
Part No		PAR #:	Fault Cat	egory:	_ NCR: Yes	No DQA :		_ Date:			
	R	esolution:	on:	QA: N/C Closed: Date:							
NCR:		\	WORK ORE	DER NON-CONFORMA	NCE (NCR)					
DATE	STEP	Description of NC		Corrective Action Section		Verificat	ification Approval		Approval		
DATE	SIEF	Section A	Initial Action Description Chief Eng Chief Eng		Sign & Date	Section C		Chief Eng	QC Inspector		
	:										
······································											
			·		·						
						•					

Picklist Print

Tuesday, October 19, 2010 2:52:58 PM

Work Order ID: 63062

Parent Item:

D3941-12

Parent Item Name: Rubber Cushion



Start Date: 10/19/2010

Required Date: 10/26/2010

Page 1

Start Qty: 5.00

Required Qty: 5.00


Comments:

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3941 Rubber Cushion		Manufactured	No			100	f	65.0000	I	5.263158	/10/	20	
				<u>Location</u> ST408		Loc (<u>Qty</u> 65	Loc Code					
					8512		65			5,262	158		

W/O:					3				
DATE	STEP	PROC	PROCEDURE CHANGE					Approval Chief Eng / Prod Mgr	Approval QC Inspector
								•	
									'
		·							
Part No	•	PAR #:	_ Fault Categ	jory:	NCR: Yes	No DQA	\:	Date:	
Resolution:			_ Disposition	QA: N/C C	Date:				
NCR:		W	ORK ORDE	R NON-CONFORMA	NCE (NCF	₹)			
DATE	CTED	Description of NC Section A		Corrective Action Section		Verific	ation	Approval Chief Eng	Approval
DATE	STEP		Initial Chief Eng	Action Description Chief Eng	Sign a	& Section			QC Inspector
							•		
						,			

SPECIFICATION CONTROL DRAWING





SHOP COPY **RETURN TO ENGINEERING UNCONTROLLED COPY** SUBJECT TO AMENDMENT

WITHOUT NOTICE

<u>D3941-XX RUBBER CUSHION</u> (XX = LENGTH OF RUBBER CUSHION IN INCHES)

DART PART NUMBER	LENGTH "XX"	MATERIAL	HARDNESS	SUPPLIER	SUPPLIER PART NUMBER	OVERALL HEIGHT	SLOT HEIGHT "SH"	EDGE THICKNESS	GAP WIDTH "G"	OVERALL WIDTH	WEIGHT
D3941-12	12	BUTADIENE STYRENE	DUROMETER 70	SPAENAUR	RW-102	0.313	0.25	0.047	0.031	0.125	0.01 LBS
D3941-40	40	BUTADIENE STYRENE	DUROMETER 70	SPAENAUR	RW-102	0.313	0.25	0.047	0.031	0.125	0.03 LBS

Α	NEW IS:	SUE		15	09.05.04		
REV.			DESCRIPTION	BY	DATE		
DESIG	7	16	DART AEROSP	ACE L	ſD		
DRAW	N	\$	HAWKESBURY, ONTAR				
CHECK	ŒD	455	DRAWING NO.		REV. A		
MFG. A	PPR.	E.	D3941		SHEET 1 OF 1		
APPRO	OSVED	#	TITLE		SCAL		
DE API	PR.	-//-	RUBBER CUSHION		NTS		
DATE	09.0	5.04	COPYRIGHT © 2009 BY DART THIS COCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLE HOT TO BE USED FOR ANY PURPOSE OR COPPED OR COMMENT	O ON THE EXPRESS	CONDITION THAT IT IS		

C

NOTES:

1) MATERIAL: N/A
2) FINISH: N/A
3) TOLERANCES: PER DART QSI 018 UNLESS OTHERWISE NOTED
4) UNITS: INCHES UNLESS OTHERWISE NOTED
5) BREAK SHARP EDGES: N/A
6) IDENTIFICATION: N/A
7) WEIGHT: SEE TABLE

С

		The state of the s								~_~				
W/O:			W	ORK ORDER CH	ANGES					·				
DATE	STEP	PRO		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector						
	\													
					_									
Part No	:	PAR #:	Fault Cat	egory:	NC	R: Yes I	No DQA	۱:	_ Date: _					
	Resolution: Disposition:						QA: N/C Closed: Date:							
NCR:		:	WORK ORE	DER NON-CONFO	PRMANCE	(NCR)							
DATE	CTED	Description of NC	Corrective Action Sec				Verific	ation	Approval	Approval				
DATE	STEP	Section A	Initial Chief Eng	Action Descrip	otion	Sign & Date		Section C	Chief Eng	QC Inspector				
								1						
					· · · · · · · · · · · · · · · · · ·									

	1 [1 1			· .	1		1	I				